## MINIO

**DATE:** August 22, 2001

TO: Mr. John Godden, Project Manager, BC&L Pavement Services

FROM: Steve Welland

RE: Pavement Rehabilitation Project, North Dakota Airports

## John:


Thank you for your recent phone call. Enclosed please find the pavement skid-testing surmary as requested. The test results are an average of three skid tests for each surface condition. As you may notice, the results at the Mott and Mohall airports indicated an increase in braking efficiency. These airports have a seal coat surface over the existing eavenent. The sealer helped hold the surface together without allowing breaking of the seal coat surface.

surface together without allowing breaking of the seal coal curface.

Also included are the test results of the physical properties for sealer/ rejuvenator for your information. Sample #1 is being retested from a companion sample taken at the same time. The airport managers I spoke with are satisfied with the product. We have a successful project.

Keep me updated on any product information in the future.

Thanks again, Steve



July 24, 2001

Mr. Brian Schuck, Program Manager Federal Aviation Administration District Office 2301 University Drive, Building 23B Bismarck, ND 58504

Re: Skid Resistance Testing Summary

Payement Rehabilitation Work

General Aviation Airports - Various Locations in North Dakota

AIP No. 3-38-0000-01

## Dear Brian:

Enclosed please find the results of the skid resistance testing performed on the pavements at the above named airports. As result of this testing, it can be determined that there is no depreciable loss in braking efficiency with the use of this coal-tar sealer rejuvenator on the pavements tested.

Please contact me should you have any questions or comments. Thank you.

Sir derely,

Kahmas, Lee & Jackson

Steven B. Weiland Senior Technician

c. Mark Holzer, ND Aeronautics Commission Bruce Batzer, Astech Corporation Steve Aldinger, Interstate Engineering, Inc. File

## **Friction Testing Summary General Aviation Airports** Various Locations in North Dakota

Location

Date Surface Surface Surface Surface (Dry) (Dry) (Wet) (Wet) 7/20/01 Carrington Municipal Airport 0.40 0.95 0.84 0.81 0.77 Ellendale Municipal Airport 0.40 0.96 0.83 7/19/01 0.86 0.85 Garrison Municipal Airport 7/23/01 0.40 1.00 0.86 1.00 0.99 7/20/01 Grafton Municipal Airport 0.40 0.90 0.83 0.85 7/19/01 Gwinner Municipal Airport 0.40 0.95 0.84 0.84 0.8 7/23/01 Hazen Regional Airport 0.98 0.40 0.94 0.93 0.93

0.40

40

0/0

0.40

0.40

Minimum

Untreated

0.84

0.85

0.95

1.00

0.85

Average Friction Value (Mu)

Treated

**N**93

0.92

0.77

0.94

0.75

Untreated

0.88

0.86

0.86

0.96

0.81

Treated

0.89

0.89

0.73

0.86

0.92

Water Application Rate: 0.45 Gal./S.Y.

Test Area: 25'x 8' Test Strip: 200'x 8'

7/23/01

7/23/01

7/19/01

7/23/01

7/19/01

Equipment: Tapley Mechanical Decelometer

Mohall Municipal Airport

Mott Municipal Airport

Oakes Municipal Airport

Dickinson Municipal Airport

amestown Municipal Airport

Steven B. Weiland

Kadrmas, Lee & Jackson

Tapley Readings	
0.65 - Above	Excellent
0.55 - 0.65	Good
0,45 - 0,50	Good/Fair
0.40	Fair
0.35	Fair/Poor
0.25 - 0.30	Poor
0.20 - Below	. Nil







